## 1/2




FIG. 1

## 2/2

A A	АВ	ВВ	AA	A 
2 x 8A 6 x 3A 4 x 1A 12 outputs	2 x 8A 7 x 3A 5 x 1A 14 outputs	2 x 8A 8 x 3A 6 x 1A 16 outputs	3 x 8A 9 x 3A 6 x 1A 18 outputs	•
3 x 8A 10 x 3A 7 x 1A 20 outputs	B A 3 x 8A 11 x 3A 8 x 1A 22 outputs		B B B 3 x &A 12 x 3A 9 x 1A 24 outputs	
4 x 8A 12 x 3A 8 x 1A 24 outputs	<u>A</u> [A]	4 x 8A 13 x 3A 9 x 1A 26 outputs	АВ	